

Reinforced Scraper Mounting Shaft.

Buhler
Customer Service
Grinding &
Dispersion.

For Three-Roll Mills SDV- and SDVE- 1100 and 1300.



On a rare occasion, the welded stop on existing mounting shafts might fail. This is because the run-off plate carrying product is pulled too quickly against the stop. The

welded stop could be weakened by the heavy load or, worst case, even torn off.

Buhler's Scope of Services:

As part of our maintenance plan, we are able to offer you the reinforced mounting shaft including the two supports.

Optional:

If necessary, you might request a specialist to mount the new parts.

Features:

- Resistant to corrosion
- More fail-safe system
- Higher load capacity
- Increased safety

Our Proposal includes the following services:

- Delivery of a complete mounting shaft assembly
- Delivery of both supports including centering pins and screws

Price:

Price upon request.

Bühler AG
Corporate Headquarters
Customer Service
CH - 9240 Uzwil, Switzerland
customerservice@buhlergroup.com
www.buhlergroup.com

